

[Print](#)**SHIP DETAIL**

Ship Name	AMY	Shiptype	General Cargo Ship
IMO/LR No.	9213715	Gross	1,499
Call Sign	V2OF7	Deadweight	1,786
MMSI No.	304108000	Year of Build	2000
Flag	Antigua & Barbuda	Status	In Service/Commission
Operator	Amy GmbH & Co KG	Shipbuilder	Daewoo-Mangalia

**COMMERCIAL HISTORY**☐ Show extended history

Date	Name	Flag	Group Owner	Operator	Manager	Registered Owner	DOC	Price
2015-01	AMY							
2014-12		Antigua & Barbuda		Amy GmbH & Co KG	Amy GmbH & Co KG	Amy GmbH & Co KG	Maritime Management Cuxhaven	
2011-09							CUXSHIP Management GmbH	
2003-11		Germany						
2001-10							Frank Dahl Reederei eK	
2000-11		Antigua & Barbuda	Dahl F	Frank Dahl Reederei eK	Frank Dahl Reederei eK	Marlin GmbH & Co KG		
2000-00	Marlin				Wagenborg Shipping BV			

Originally Marlin

CONSTRUCTION OVERVIEW

Shiptype	General Cargo Ship	Built	2000	GT	1,499	Deadweight	1,786
----------	---------------------------	-------	-------------	----	--------------	------------	--------------

SHIP BUILDER

2000-11 Daewoo-Mangalia Heavy Industries S.A. - Mangalia (Hull) Yard/hull No.: 1025
 2000-11 Scheepswerf Pattje B.V. - Waterhuizen Yard/hull No.: 439

STATUS

Date	Status
2000-11-17	In Service/Commission
2000-06-24	Launched
2000-04-01	Keel Laid
1999-06-00	On Order/Not Commenced

CONSTRUCTION DETAIL

Statcode5:A31A2GX; Ship Type Group:General Cargo <=4,999 dwt; Hull Material:Steel; Hull Connections:Welded;
 Decks:1 dk

SERVICE CONSTRAINTS

Trading, Commercial; River/Canal/Dock; Deep Sea; Other Geographical Limits

ALTERATIONS & CONVERSIONS**DIMENSIONS**

Length Overall	80.250	Length (BP)	77.150
Length (Reg)	0.000	Bulbous Bow	No
Breadth Extreme	0.000	Breadth Moulded	11.420
Draught	3.200	Depth	3.800
Height	0.000		
Displacement	2623	T/CM	0.0

TONNAGES

Tonnage Type	One tonnage, unspecified	Tonnage System	New System (International 1969)
Effective Date	2000-00	Effective Date	2000-00

ARRANGEMENT

Structure	Sequence (Bow to Stern)	Position	Type	Material	Length	Breadth
Compartment	01	Centre Or Only	Dry Cargo Hold	Steel (Unspecified)		
Hatch	01	Centre Or Only	Normal Hatch	N/A		

SISTER SHIPS

At most, the first fifty sister ships are returned. [Click here to return all sister ships into Search Results.](#)

LRNO	Ship Name	Status	Deadweight	GT	Built	Type	Yard No	Main Engine
9213715	AMY	IN SERVICE/COMMISSION	1786	1499	2000-11	General Cargo Ship	1025	TAMD163A
9213703	LEYLA	IN SERVICE/COMMISSION	1802	1499	2000-09	General Cargo Ship	1024	TAMD163A
9218533	RMS CUXHAVEN	IN SERVICE/COMMISSION	1797	1499	2001-05	General Cargo Ship	1026	TAMD163A

SUPPLEMENTARY FEATURES**CARGO OVERVIEW**

Grain	2,666	Bale	2,666	Liquid	0	Gas	0
TEU	0	TEU 14t	0	Insulated	0		

COMPARTMENTS

1 STEEL (UNSPECIFIED) Centre Or Only Dry Cargo Hold(s)

TANKS**HATCHES**

1 Centre Or Only Normal Hatch 0.00m long by 0.00m breadth

CAPACITIES

Grain 2,666; Bale 2,666; Segregated Ballast 1,341

SPECIALIST**CARGO HANDLING GEAR****RO-RO (LANES, RAMPS & DOORS)****TOWAGE****MISCELLANEOUS****MACHINERY OVERVIEW**

2 oil engines reduction geared to screw shafts driving 2 FP propellers at 275 rpm Total Power: Mcr 742kW (1,008hp) Service Speed: 10.00kts

PRIME MOVER DETAIL

Design: Volvo Penta, **Engine Builder:** AB Volvo Penta - Sweden
2 x TAMD163A, 4 Stroke, Single Acting, In-Line (Vertical)
 6 Cy. 144 x 165, Mcr: 371 kW (504 hp) at 1,800 rpm

AUXILIARY ENGINES

Design: Valmet, **Engine Builder:** Valmet
3 x 320DSG, 4 Stroke 3Cy.
 108 x 120, Mcr: 70 kW

Aux Generator: 3 x 50kW 220/380V a.c.

BUNKERS

Fuel:Capacity - Distillate Fuel: 83 cu m

THRUSTERS

Thrusters: 1 Water jet (f) 280kW(381bhp)

INSPECTIONS & DETENTIONS

Data as reported by Port State Control Authorities							
Authority	Status	Date	Place	Name	Flag	Class	Owner
Paris MOU	Detailed Inspection	2018-05-07	Goole	Amy	Antigua And Barbuda	DNV GI As	
Paris MOU	Detailed Inspection	2017-06-23	Goole	Amy	Antigua And Barbuda	DNV GI As	
3 Defects: Propulsion and auxiliary machinery - Propulsion main engine - Not as required Propulsion and auxiliary machinery - Propulsion main engine - Not as required Certificates & Documentation - Crew Certificate - Seafarers' employment agreement (SEA) - Not properly filled							
Paris MOU	Detailed Inspection	2016-09-16	Goole	Amy	Antigua And Barbuda	DNV GI As	
2 Defects: Certificates & Documentation - Crew Certificate - Seafarers' employment agreement (SEA) - Not properly filled Life saving appliances - Rescue boats - Not properly maintained							
Paris MOU	Initial Inspection	2015-09-11	Rotterdam	Amy	Antigua And Barbuda	Germanischer Lloyd	
Paris MOU	Detailed Inspection	2014-09-11	Keadby	Marlin	Antigua And Barbuda	Germanischer Lloyd	
8 Defects: Safety of Navigation - Magnetic compass - Not as required Certificates & Documentation - Document - Records of rest - Entries missing Safety of Navigation - Charts - Not updated Labour Conditions - Accommodation, recreational facilities, food and catering - Ventilation (Working spaces) - Inoperative Labour Conditions - Health protection, medical care, social security - Guards - fencing around dangerous machinery parts - Missing equipment Fire safety - Fire doors/openings in fire-resisting divisions - Not as required Propulsion and auxiliary machinery - Gauges, thermometers, etc - Inoperative							
Paris MOU	Detailed Inspection	2014-05-06	New Ross-Raheen/Roberson	Marlin	Antigua And Barbuda	Germanischer Lloyd	
1 Defect: Working and Living Conditions - Working Conditions - Safe means of access - Not as required							
Paris MOU	Initial Inspection	2013-06-22	Goole	Marlin	Antigua And Barbuda	Germanischer Lloyd	
Paris MOU	Initial Inspection	2012-07-30	Rotterdam	Marlin	Antigua And Barbuda	Germanischer Lloyd	
Paris MOU	Initial Inspection	2011-09-22	Farsund	Marlin	Antigua And Barbuda	Germanischer Lloyd	
2 Defects: Other - Other (MARPOL operational) - Other Life saving appliances - Inflatable liferafts - Not properly stowed							
Paris MOU	Initial Inspection	2010-11-19	Goole	Marlin	Antigua And Barbuda	Germanischer Lloyd	
3 Defects: Life saving appliances - Lifebuoys - Not as required Safety of navigation - Other (navigation) - Other Life saving appliances - Inflatable liferafts - Not properly stowed							
Paris MOU	Initial Inspection	2010-05-04	Kristiansand	Marlin	Antigua And Barbuda	Germanischer Lloyd	
Paris MOU	More detailed inspection	2009-10-09	Ghent	Marlin	Antigua And Barbuda	Germanischer Lloyd (GI)	
Paris MOU	Initial inspection	2009-04-07	Szczecin	Marlin	Antigua And Barbuda	Germanischer Lloyd (GI)	
Paris MOU	More detailed inspection	2009-02-18	Rouen (PA)	Marlin	Antigua And Barbuda	Germanischer Lloyd (GI)	
2 Defects:							

Paris MOU	Initial inspection	2007-06-06	Teesside	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Initial inspection	2006-12-01	Vasteras	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Initial inspection	2006-01-17	Solvesborg	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	More detailed inspection	2005-11-11	Kaliningrad	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
8 Defects: Cargoes - Cargo securing manual - Not approved MARPOL annex I - Oil record book - Not properly filled MARPOL annex I - SOPEP - Not approved Crew certificates - Certificates for master and officers - Not as required Structural safety - Means of escape - Blocked Structural safety - Marking of IMO number - Not as required Fire safety measures - Emergency escape breathing device - Not properly marked Radiocommunications - Other (radiocommunication) - Other							
Paris MOU	Initial inspection	2005-05-12	Nantes-Saint Nazaire (PA)	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Inspection	2004-10-19	Fredericia	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Inspection	2004-09-09	Hartlepool	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
4 Defects: Safety of navigation - Charts - Expired Safety of navigation - Magnetic compass - Missing Crew certificates - Certificates for master and officers - Expired Fire safety measures - Emergency fire pump - Not as required							
Paris MOU	Inspection	2004-03-31	Kaliningrad	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
2 Defects: Operational deficiencies - Fire control plan - Not updated Life saving appliances - Lifebuoys - Not properly marked							
Paris MOU	Inspection	2003-09-15	Solvesborg	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Inspection	2003-03-12	Kaliningrad	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Inspection	2002-08-20	Delfzijl	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Inspection	2002-06-27	Brunsbüttel	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Inspection	2002-05-24	Ghent	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
2 Defects: Life saving appliances - Evaluation, testing and approval - Not specified Life saving appliances - Other (life saving) - Not specified							
Paris MOU	Inspection	2002-03-26	Brunsbüttel	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
1 Defect: Crew certificates - Certificates for master and officers - Not specified							
Paris MOU	Inspection	2002-01-21	Fredericia	Marlin	Antigua And Barbuda	Germanischer Lloyd (GL)	
Paris MOU	Inspection	2001-03-22	Sandnessjoen	Marlin	Antigua And Barbuda	Germanischer Lloyd (Germany)	

INSPECTED CERTIFICATES

Data as reported by Port State Control Authorities in last 12 Months

Certificate	Issue Date	Expiry Date	Issued By	Inspected
Bunker Oil Pollution Damage	2018-02-24	2019-02-20	Antigua and Barbuda	2018-05-07 by Paris MOU
Cargo Ship Safety Construction	2018-02-03	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU
Cargo Ship Safety Equipment	2016-01-26	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU
Cargo Ship Safety Radio	2016-01-26	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU

Document of Compliance Dangerous Goods	2018-02-03	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU
International Air Pollution Prevention	2018-02-03	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU
International Anti-Fouling System	2018-02-03		DNV GL AS	2018-05-07 by Paris MOU
International Oil Pollution Prevention (IOPP)	2016-01-26	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU
International Sewage Pollution Prevention	2016-02-03	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU
International Ship Security	2015-08-03	2020-06-13	DNV GL AS	2018-05-07 by Paris MOU
Load Line	2016-01-26	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU
Maritime Labour Certificate	2015-08-03	2020-06-12	DNV GL AS	2018-05-07 by Paris MOU
Minimum Safe Manning Document	2017-12-30		Antigua and Barbuda	2018-05-07 by Paris MOU
Other Certificate	2016-01-26	2020-10-31	DNV GL AS	2018-05-07 by Paris MOU
Safety Management Certificate	2015-08-03	2020-06-13	DNV GL AS	2018-05-07 by Paris MOU
Tonnage	2018-02-03		DNV GL AS	2018-05-07 by Paris MOU

SAFETY MANAGEMENT CERTIFICATES

Sequence	Current				
Shipname (Reported)	Amy	Flag (Reported)	Antigua & Barbuda	DOC Company	Maritime Management Cuxhaven
Type	Convention	Auditor	DNV GI	Issuer	DNV GI
Date of Issue	2015-08-03	Date of Expiry	2020-06-13		
Sequence	Historical				
Shipname (Reported)	Amy	Flag (Reported)	Antigua & Barbuda	DOC Company	Maritime Management Cuxhaven
Type	Convention	Auditor	DNV GI	Issuer	DNV GI
Date of Issue	2014-12-30	Date of Expiry	2015-06-29		
Sequence	Historical				
Shipname (Reported)		Flag (Reported)	Antigua & Barbuda	DOC Company	CUXSHIP Management GmbH
Type		Auditor	GL	Issuer	GL
Date of Issue	2011-09-20	Date of Expiry	2016-09-17		
Sequence	Historical				
Shipname (Reported)		Flag (Reported)	Antigua And Barbuda	DOC Company	Frank Dahl Reederei eK
Type	Convention	Auditor	GL	Issuer	Germanischer Lloyd
Date of Issue	2006-11-17	Date of Expiry	2011-09-17		
Sequence	Historical				
Shipname (Reported)	Marlin	Flag (Reported)	Antigua And Barbuda	DOC Company	Frank Dahl Reederei eK
Type	Convention	Auditor	GL	Issuer	GL
Date of Issue	2006-09-06	Date of Expiry	2007-02-05		
Sequence	Historical				
Shipname (Reported)	Marlin	Flag (Reported)	Antigua And Barbuda	DOC Company	Frank Dahl Reederei eK
Type	Convention	Auditor	GL	Issuer	GL
Date of Issue	2001-10-31	Date of Expiry	2006-09-17		

THREE YEAR EVENT SUMMARY

Significant Event	Last 12 months	Between 1 and 2 years ago	2-3 years ago
Casualties	0	0	0
Class status changes	0	0	0
Detentions	0	0	0
DOC certificates	0	0	0
Flag changes	0	0	0
Group Owner changes	0	0	0
Inspections	1	2	1
Name changes	0	0	0

CASUALTIES

To add this optional module to your subscription simply click here

Nationality	Total ratings	Total Officers	Total Crew
Filipino	2	0	2
Polish	1	1	2
Russian	0	2	2

EVENT TIMELINE

Date	Significant Events
201805	PSC Inspected
201706	PSC Inspected
201609	PSC Inspected
201509	PSC Inspected
201508	SMC Certificate issued by DNV GL Expires 20200613
201501	Name changed to AMY
201412	Flagged by Antigua and Barbuda, SMC Certificate issued by DNV GL Expires 20150629, Operator Amy GmbH and Co KG, Technical Manager Maritime Management Cuxhaven, Owner Amy GmbH and Co KG, Ship Manager Amy GmbH and Co KG
201409	PSC Inspected
201405	PSC Inspected
201306	PSC Inspected
201207	PSC Inspected
201109	PSC Inspected, SMC Certificate issued by GL Expires 20160917, Technical Manager CUXSHIP Management GmbH
201011	PSC Inspected
201005	PSC Inspected
200910	PSC Inspected
200904	PSC Inspected
200902	PSC Inspected
200807	PSC Inspected
200706	PSC Inspected
200612	PSC Inspected
200611	SMC Certificate issued by Germanischer Lloyd Expires 20110917
200609	SMC Certificate issued by GL Expires 20070205
200601	PSC Inspected
200511	PSC Inspected
200505	PSC Inspected
200410	PSC Inspected
200409	PSC Inspected
200403	PSC Inspected
200311	Flagged by Germany
200309	PSC Inspected
200303	PSC Inspected
200208	PSC Inspected
200206	PSC Inspected
200205	PSC Inspected
200203	PSC Inspected
200201	PSC Inspected

200011	Flagged by Antigua and Barbuda, Flagged by Germany, Status changed to In Service/Commission, Operator Frank Dahl Reederei eK, Owner Marlin GmbH and Co KG, Ship Manager Frank Dahl Reederei eK, Group Owner Dahl F
200006	Status changed to Launched
200004	Status changed to Keel Laid
200000	Name changed to Marlin, Contemplated GL, Ship Manager Wagenborg Shipping BV
199906	Status changed to On Order/Not Commenced

PHOTOGRAPHS


[Play Slideshow](#)
[< Previous Photo](#) [Next Photo >](#)


Photo 1 of 18

Amy

Photo Date:

2016-08-13

Copyright: Olaf

Schmidt

AIS POSITION

To add this optional module to your subscription simply click here

SHIP PERFORMANCE



This data is brought to you in cooperation with Marine Benchmark.

Vessel operation analysis

The data below is for demo purposes only. To view real data you will need to add the Benchmark Module to your subscription.

Ship Performance Data
No operation data available for this ship.

i Demo data shows how the data are formatted in the full product. For oldest period sharp data is shown. Please contact IHS Maritime for any question or subscriptions. Time moving/still is identified as time in speed over/under 1 kn. Average speed is calculated for time in speed over 6 kn. Time moving in SECA area is percent of total time in full month and not percent of time in SECA. For more detailed, longer analysis or SECA area analysis please contact Marine Benchmark.

Ship Performance Data

No trading area data available for this ship.

i Demo data shows how the data are formatted in the full product. For oldest period sharp data is shown. Please contact IHS Maritime for any question or subscriptions. Time in area is defined as all time still or moving. The globe is divided into 9 highly aggregated trading areas (for area definitions, please see the help file under help tab or in a link at the top of this section). For more detailed geographical analysis, first down to 18 well defined and market based trading areas, containing US gulf, Sain Lawrence seaways etc. Or any custom defined area on the globe please contact Marine Benchmark.

© 2018 IHS Global Limited. IHS Global Limited assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has a contract with IHS Global Limited and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.